

Network Working Group
RFC #256
NIC #7697
Categories: B.1
Updates: None
Obsoletes: None

B. Cosell
BBN
3 November 1971

IMPSYS Change Notification

We will shortly install (or perhaps will have already installed) a new version of the IMP system, Version 2513. The new version incorporates two principal changes:

1. A Host will be prevented from sending any messages into the Network for between 40 seconds and a minute and a quarter after he comes alive (this has been changed from between 30 seconds and a minute).
2. The IMP has been given the ability to test its Host interfaces under control of the NCC. This will help us isolate the trouble when the IMP Host communication path is faulty.

BC/jm

[This RFC was put into machine readable form for entry]
[into the online RFC archives by BBN Corp. under the]
[direction of Alex McKenzie. 12/96]

